





The Tempest 200 has 4 mounting screws, the PCB in the top of the case, the CR2032 battery, and the gasket and bottom of case (from left to right). When installing the battery, match up the “+” markings on the battery holder and the battery as you insert the battery. When seated properly, it looks like the example below.



Finally, install the 4 screws to hold the entire Tempest 200 together.

